

 स्वातंत्र्याचा अमृत महोत्सव	Executive Engineer, Public Works (South) Division, Pune Central Building Compound, Pune 411001		
	Phone No. 020-26124295	Email ID- integratedpune.ee@mahapwd.gov.in	
Out word No.DB/ Building Certificate / 6018 / 2026		Date:- 13/07/2026	

BUILDING SAFETY CERTIFICATE

Subject:- Requirement of Building Safety Certificate for "MIS SCHOOL",

Survey No. 29/31/32 /43/A/1 Amenity SPAC -1 ,Maan,Tal. Mulshi,Dist.Pune —411057.

References:-

1. Letter submitted by the Principal, MIS SCHOOL, Survey No. 29/31/32 /43/A/1 Amenity SPAC -1 ,Maan,Tal. Mulshi,Dist.Pune —411057, dated 23/06/2026.
2. Site Inspection Report submitted by the Sub-Divisional Engineer, Public Works Sub-Division, Mulshi.vide Letter No. DB/ 674 /2026 dated 10/07/2026.
3. Development Permission and Commencement Certificate issued by PMRDA vide Letter No. BMU/Mouje-Man/Sr.No.29/31/32/43/A/1/Pr.Kr.1130/23-24/5698, dated 27/10/2023.
4. Occupancy Certificate issued by PMRDA vide Approval No. PMRDA/FO/2025/APL/00040, dated 20/08/2025.
5. Fire Safety Certificate issued by the Chief Fire Officer, PMRDA vide Letter No. अग्निशमन/अंतिमना-दाखला/मुळशी/2025-26/139, dated 23/07/2025.
6. Quality and Technical Supervision Certificate issued by M/s. Vilas Javdekar Eco Shelters Pvt. Ltd., dated 23/06/2026.
7. Structural Stability Certificate issued by Shri Jayant Inamdar, Structural Consultant, Strudcom Consultants Pvt. Ltd., Licence No. PMRDA/STR.ENG/430/2024-26, vide Letter No. 12177/STAB/2024/R2, dated 22/11/2024.

It is hereby certified that the existing building of "MIS SCHOOL", Survey No. 29/31/32 / 43/A/1 Amenity SPAC -1 ,Maan,Tal. Mulshi,Dist.Pune —411057, comprises the following block / floors:

Detail of Block(s) in school	Block (1)
"MIS SCHOOL", Survey No. 29/31/32 / 43/A/1 Amenity SPAC-1 ,Maan,Tal. Mulshi,Dist.Pune—411057	Ground Floor + 8 Upper Floors

The building is owned and occupied by "MIS SCHOOL", Survey No. 29/31/32 / 43/A/1 Amenity SPAC -1 , Maan,Tal. Mulshi,Dist.Pune —411057 . The building have complied with the prescribed Building Safety requirements and was verified by the officers of the Public Works Department on 10/07/2026 in the presence of the Principal of "MIS SCHOOL", Survey No. 29/31/32 / 43/A/1 Amenity SPAC -1 , Maan,Tal. Mulshi,Dist.Pune —411057 and that the building is Structurally Safe and fit for Occupancy up to classes XII with Effect from Date-13/07/2026 for a period of 01 year in accordance with rule.



(A.R.Bhandare)

Executive Engineer,
P.W.(South)Division,Pune

Copy:- Principal of "MIS SCHOOL", Survey No. 29/31/32 / 43/A/1 Amenity SPAC -1, Maan,Tal.Mulshi,Dist.Pune—411057.